



Here comes the Xtreme connection for Cas Interface 2.

You have to build the Slow Down board because the Cas 2 signals might be too fast for your Xtreme receiver. In this case and only in this case the Slow Down board must be done.



Pin 16 - Cas Interface 2 Connector



Slow Down Circuit for Xtreme U1,U2 = 74HC04 receivers Only!! U1,U2 = 74HC04 R1 = 100 Ohm R2 = 10K Ohm