

FRITZ!Box Event Log, Status of Saturday, 4 October 2014 19:15:58**WLAN** Log registrations and deregistrations

04.10.14	19:14:05	Wireless LAN device registered: Reactivating wireless LAN at full power.
04.10.14	19:14:02	No wireless LAN device registered any more: Reducing power consumption.
04.10.14	18:59:00	Wireless LAN device registered: Reactivating wireless LAN at full power.
04.10.14	18:57:58	No wireless LAN device registered any more: Reducing power consumption.
04.10.14	18:27:55	Wireless LAN device registered: Reactivating wireless LAN at full power.
04.10.14	18:27:32	No wireless LAN device registered any more: Reducing power consumption.
04.10.14	18:18:00	Wireless LAN device registered: Reactivating wireless LAN at full power.
04.10.14	18:14:17	No wireless LAN device registered any more: Reducing power consumption.
04.10.14	17:23:40	Wireless LAN device registered: Reactivating wireless LAN at full power.
04.10.14	17:23:29	No wireless LAN device registered any more: Reducing power consumption.
04.10.14	17:13:55	Wireless LAN device registered: Reactivating wireless LAN at full power.
04.10.14	17:13:52	No wireless LAN device registered any more: Reducing power consumption.
04.10.14	17:04:10	Wireless LAN device registered: Reactivating wireless LAN at full power.
04.10.14	17:04:07	No wireless LAN device registered any more: Reducing power consumption.
04.10.14	16:34:30	Wireless LAN device registered: Reactivating wireless LAN at full power.
04.10.14	16:31:26	No wireless LAN device registered any more: Reducing power consumption.
04.10.14	16:12:12	Wireless LAN device registered: Reactivating wireless LAN at full power.
04.10.14	16:05:35	No wireless LAN device registered any more: Reducing power consumption.
04.10.14	16:00:22	New wireless LAN device registered for the first time. Throughput 54 Mbit/s. MAC address: 34:AF:2C:39:1C:3B.
04.10.14	16:00:13	Wireless LAN transmission quality increased by reduced channel bandwidth.
04.10.14	16:00:00	Wireless LAN was enabled by night service.
04.10.14	12:00:00	Wireless LAN was disabled by night service.
04.10.14	10:03:13	No wireless LAN device registered any more: Reducing power consumption.
04.10.14	10:00:13	Wireless LAN transmission quality increased by reduced channel bandwidth.
04.10.14	10:00:00	Wireless LAN was enabled by night service.
04.10.14	02:00:00	Wireless LAN was disabled by night service.
04.10.14	01:43:08	No wireless LAN device registered any more: Reducing power consumption.
04.10.14	00:02:28	New wireless LAN device registered for the first time. Throughput 65 Mbit/s. MAC address: 64:76:BA:4E:A0:96.
04.10.14	00:02:28	Wireless LAN device registered: Reactivating wireless LAN at full power.
03.10.14	23:51:12	No wireless LAN device registered any more: Reducing power consumption.
03.10.14	23:41:53	Wireless LAN device registered: Reactivating wireless LAN at full power.
03.10.14	23:41:42	No wireless LAN device registered any more: Reducing power consumption.
03.10.14	23:32:08	Wireless LAN device registered: Reactivating wireless LAN at full power.
03.10.14	23:31:57	No wireless LAN device registered any more: Reducing power consumption.
03.10.14	23:22:23	Wireless LAN device registered: Reactivating wireless LAN at full power.
03.10.14	23:22:12	No wireless LAN device registered any more: Reducing power consumption.
03.10.14	23:12:38	Wireless LAN device registered: Reactivating wireless LAN at full power.
03.10.14	23:08:16	No wireless LAN device registered any more: Reducing power consumption.
03.10.14	22:56:43	Wireless LAN device registered: Reactivating wireless LAN at full power.
03.10.14	22:52:21	No wireless LAN device registered any more: Reducing power consumption.
03.10.14	22:40:49	Wireless LAN device registered: Reactivating wireless LAN at full power.
03.10.14	22:40:38	No wireless LAN device registered any more: Reducing power consumption.
03.10.14	22:31:04	Wireless LAN device registered: Reactivating wireless LAN at full power.
03.10.14	22:30:53	No wireless LAN device registered any more: Reducing power consumption.
03.10.14	22:21:19	Wireless LAN device registered: Reactivating wireless LAN at full power.
03.10.14	22:20:17	No wireless LAN device registered any more: Reducing power consumption.
03.10.14	22:11:37	Wireless LAN device registered: Reactivating wireless LAN at full power.
03.10.14	22:09:42	No wireless LAN device registered any more: Reducing power consumption.
03.10.14	21:52:09	Wireless LAN device registered: Reactivating wireless LAN at full power.
03.10.14	21:51:58	No wireless LAN device registered any more: Reducing power consumption.
03.10.14	09:00:13	Wireless LAN transmission quality increased by reduced channel bandwidth.
03.10.14	09:00:00	Wireless LAN was enabled by night service.
03.10.14	03:00:00	Wireless LAN was disabled by night service.
02.10.14	22:26:45	Wireless LAN device registered: Reactivating wireless LAN at full power.
02.10.14	22:26:33	No wireless LAN device registered any more: Reducing power consumption.
02.10.14	22:17:00	Wireless LAN device registered: Reactivating wireless LAN at full power.
02.10.14	22:16:48	No wireless LAN device registered any more: Reducing power consumption.