


Connect to the ground (metal body)



How to do

1. Run jKeys.exe
2. Click on **Flash Tools**
3. The message coming up with "Flash tools....." DO not click OK
4. connect printer cable to pc
5. Turn Sammy on
6. Now Click **OK**
7. Click on **Erase Flash**
8. After you erase Flash Click on **Write Flash**
9. The program will ask for bin file just open (dsr9500.bin)
10. Wait until all blue squares are finished
11. Take cable out of PC
12. Turn off The Sammy
13. Turn on the Sammy now you will see that your sammy is patched

Good luck
Jojo
Sorry for my Eng